Work Order II August 24, 2010 8:40											Page 1
Revision ID:	38-042 Assembly (Basket Lid, RH)	110	Accept				S S	etup	Start Stop		
Start Date: 8/24/ Required Date: 8/30/ Reference:				Cust Item Customer			_		C4- ::4		22118 IBI (IBI (B2)
	cess Plan:	Date:/	O 2 Tooling: SPC (Y/N):		Oate: Oate:			tun	Start Stop		6614 141 111 1667 1414 118 118 188
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr	-									
100 Large Fab	Rev A Large Fab Memo		0.00				1	ا كلاً	0/0	9/21	(4 _K
Large Fab	1- cut 2- rem 3- deb 4- wel to fini	D3838-2 and D3838-ove identification manurr d D3838-2 to D3838-sh size as per dwg D3	3 and drill hole (3/16") using DTS	9437 jig and open 🖊							
ć	5- c'si	nk hole as per dwg									, .
	7- wel	d D3759-1 bushing as									
	9 aris	d bushing wold fluch	as per dwg dwg D3838								

.

ij*

Dart Ae	rospace	e Ltd							•			
W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
								,	•			
Part No: PAR #:			Fault Cate	egory:	NCR: Yes	No DQ	A:	Date: _				
	R	esolution:	Disposition	on:	QA: N/C C							
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NCF	₹)						
D.4.T.E		Description of NC			ction B Verifica			Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	🧏 Sect	tion C	Chief Eng	QC Inspector			

Work Order ID 61398

August 24, 2010 8:40:18 AM



Page 2

Item ID:

D3838-042

Accept

Setup Start

Stop



Revision ID:

Item Name:

Required Date: 8/30/10

Rib Assembly (Basket Lid, RH)

Start Date:

8/24/10

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:_____

Tooling:

Date:

Run

Start

Stop



Date: _____

SPC (Y/N):

Set Up/

Run Hours

Tool ID

Code

Reject

Reject

Insp.

Sequence ID/ Work Center ID

110

Quality Control

Operation **Description**

QC5- Inspect part completeness to step on W/O

QC9- Inspect visual per QSI004- Fusion Welds

Tool # Plan

Date: _____

Accept Qty

Qty

Number

Stamp

Memo

0.00

Quality Control

Memo

0.00

130

120

Packaging

Packaging

Identify as per dwg & Stock Location:

Memo

0.00

0.00

Sy 10/09/21 (4x)

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
								1 Tod Wigi	•				
Part No:		PAR #:	Fault Cate	jory:	NCR: Yes No DQA: Date:								
Resolution:			Disposition	:	QA: N/C Clo								
NCR:			WORK ORD	R NON-CONFORMA	NCE (NCR)							
DATE	0750	Description of NC		n B	Verific	cation	Approval Chief Eng	Approval					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector					
···													
						i.							
	I		1 1			1		F	1				

Work Ord August 24, 2010											Page 3		
Item ID: D3838-042 Revision ID:				Accept	Setup Sta								-
Item Name:	Rib Assembly	(Basket Lid, RH)							9	Stop			
Start Date: Required Date	8/24/10 : 8/30/10	Start Qty: 2.00 Req'd Qty: 2.00			Cust Item I Customer:	D:							
Reference:													
Approvals:	Process Plan:QC:		Date:	Tooling:	Date:					Start			
			Date:	SPC (Y/N):	D	Date:				Stop			
Sequence ID/ Work Center I	I D	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rejec Qty		eject umber	Insp. Stamp	-
140 		QC21- Final Inspection	- Work Order Release	0.00						10	1091	21 4	
QC Quality Control		Memo		0.00							inc		
Quanty Control									,	_ ,	10-	9-21	

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
										•			
	į								_				
Part No:		PAR #:	Fault Categ	ory:	NCR: Yes No DQA: Date:								
Resolution:			Disposition: Q			V/C Clo	sed:		Date: _				
NCR:			WORK ORDE	R NON-CONFORM	IANCE	(NCR)							
DATE	STEP	Description of NC			ction B	Verification		Approval	Approval				
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	ı C	Chief Eng	QC Inspector			
									,	·			
				a the state of the state of									
					ĺ								

3									*		Ì	
Picklist Print					· · · · · · · · · · · · · · · · · · ·							Page
lugust 24, 2010 _, 8:4	40:17 AM											
Vork Order ID: 613	398											
Parent Item: D3 Parent Item Name:	8838-042 Rib Assembly (Bask	ket Lid, RH)				III			eart Date: 8/24/		1	d Date: 8/30/10 ed Qty: 2.00
Comments:	IPP Rev:A 08-12-	-01 new issue D	D veri	fied by:EC								,
Component Item ID/ tem Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Status Issued
93759-1 	IA IBI IAI	Manufactured	No			100	Each	91.0000		2 W	10/	09/21
				Location	<u>1</u>	Loc	<u>Oty</u>	Loc Code				
				ST084			.60		_			
					56942		60		. –			
				WA			31		_			
					54072 61348		9 22		_	(4)		
//304TS0.750W.065	 65W	Purchased	No		3,3 10	100	f	44.7532	1.0317	2.172	10/0	16/15
												1

Location Loc Oty Loc Code MAT 1.4628 112398 114482 1.4628 WA 43.290385 114520 11.363385 115274 31.927

2.17 +1 (EUD BAR Scrop)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
									,				
Part No:		PAR #:	Fault Categ	gory:	NCR: Yes No DQA: Date:								
Resolution:			Disposition	n:	_ QA: N/C C	losed:		Date: _					
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)							
DATE	0750	Description of NC		on B	Verific	cation	Approval	Approval					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti	on C	Chief Eng	QC Inspector				
		Service and the service and th											

QTY -041 QTY -042 ITEM DESCRIPTION P/N D3838-041 RIB ASSY (BASKET LID, LH) RIB ASSY (BASKET LID, RH) 2 D3838-042 D3759-1 BUSHING 4 D3838-1 RIB 1 D3838-2 1 D3838-3 RIB RIB SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY SUBJECT TO AMENDMENT D3838-041 RIB ASSY (BASKET LID, LH) WITHOUT NOTICE WORK ORDER)_- 6 398 C X 10/8/24 D3838-042 RIB ASSY (BASKET LID, RH) NEW ISSUE 08.10.08 REV. DESCRIPTION BY DATE DESIGN DART AEROSPACE LTD NOTES: 1) MATERIAL: N/A HAWKESBURY, ONTARIO, CANADA DRAWN DRAWING NO. CHECKED 1) MATERIAL: N/A
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A REV. A D3838 MFG. APPR. SHEET 1 OF 3 APPROVED TITLE SCALE RIB ASSY (BASKET LID) DE APPR. NTS COPYRIGHT © 2008 BY DART AEROSPACE LTD
THIS DOCUMENT IS PRIVATE AND COMPOSED AND ABOVE OF COMPOSED ON THE EXPRESS CONCENTRATION OF THE PRIVATE OF THE PRIVAT

DATE

08.10.08

7) WEIGHT: 0.54 lbs



